



KEY NOTES

1. COORDINATE LOCATION OF M1620, PATIENT CHART HOLDER, AND ROOM SIGNAGE.
2. MOUNT A5145, HOOK, AT 1372 [4'-6"] AFF.
3. MOUNT A5145, HOOK, AT 1524 [5'-0"] AFF.
4. P3200, ELECTRONIC LAVATORY, MAY BE USED INSTEAD OF P3100, LAVATORY. FOR THE P3200 PROVIDE EITHER BATTERY POWER OR HARD WIRED CONNECTION.
5. MOVE P3100, LAVATORY, AND ACCESSORIES TO THE EAST WALL AND F0205, CHAIR, AND X3830, FILM ILLUMINATOR, TO THE WEST WALL FOR ARMY PROJECTS ONLY.

EXAM ROOM AIR FORCE (EXRG3)

CLINIC OF THE FUTURE

FLOOR/EQUIPMENT PLAN

12.08 NSM (130 NSF)

DATE: 01/28/2002

0 1000 2000



1:50 SCALE (MILLIMETERS)